VISION OF ENVIRONMENTAL HEALTH:
-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Jeff Nanney APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 7/31/2001
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: _____ PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
In front of House	0-6	Brw SCe GR FR						PS
	6-24	Yel/Brw C/Cl m-w SBK			SS, SP, SE, FI-FR			
	24-30	Yel/Brw C/Cl/SCl						
		Hit Chroma 2 mottles at 30", .25 to .3						
		* Need Backhoe pits to Consider at 30"						
Behind House	0-8"	Brw SL/SCl						PS
	8-30"	Rd/Brw C/Cl w/Yel/Brw Inclus May be "Higher dirt"						
	30"-42"	Rd/Brw C/Cl w		SBK	SS, SP, SE, FI-FR			.25
	0-8	Brw SL/SCl						PS .3
	8-30	Rd/Brw & Yel/Brw C/Cl		m-w SBK				
	30-42	Rd/Brw C/Cl		SBK				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Suitable Space (.1945)		
System Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION

OWNER: Jeff Nanney
ADDRESS: _____ 8/2/2001
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: _____ PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed ★ Still Needs French Drain

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
P1	Behind Hse	0-8	Brw SCL	GR FR					PS .2 to 19"
		8-24	Rd/Brw CL "Tiger Dirt"	m ANG FI GR S,P	w/few Yel/Brw Inclus				
		24-53	Rd/Brw SC	w SBK	massive	19"	w/Chroma 2 Use Depth Restrictions		
			Mottles at						
P2	In front	0-8"	Brw SCL	GR FR					PS .2 to 30"
		8-24	Rd/Brw SC	w-massive	w/few w-massive		Yel/Brw Mottles w/ some to many		
		30-48	Rd/Brw to Brw SC		Chroma 2 mottles at	30"			
			Yel/Brw mottles						
P3	LPP Behind house closest to road	0-9	Brw SCL						PS .2 to Fi to 30"
		9-24	Rd/Brn to Yel/Brw	C/SC	Wk to massive S,P SC				
		24-45	Rd/Brn to Yel/Brw	SC	Wk to mass S,P		Very Fi to		
		45-58"	Back into Chroma 2 mottles at			24"			
P4	In front to left	0-6	Brw SCL GR FR SS,SP						PS .25
		6-54	Yel Brw/Rd Brw WSBK SC to SCL		w/ Yel/Brw mottles at 36"+				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Usable Space (.1945)		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____