4669405342

10005

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Daniel Gibby DATE 7/3/89 ~~PERMIT NO~~ 18D

PHONE: Business _____ Home _____

LOCATION 21 N. TR 2383 (Shinnville Road) TR Pond View Rd.
At end on left. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home (DW) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area 5.89 ACRES

Character & Porosity of Soil Clay
Percolation Rate ~.4gpd/ft²
Topography 4J 6070
Depth to Water Table 4'+
Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

POND VIEW DRIVE

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓) existing
Public ( )

Installed by Julian Bowles

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH, RS.

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Andrew C. Reece, R.S. DATE 7/3/89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

10005 4:30

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Daniel Gibby DATE May 31, '89 PERMIT NO.

PHONE: Business Home

LOCATION 21 N. TR 2383 (Shinnville Road) TR Pond View Dr. at end on left S. R. No.

SUBDIVISION NAME LOT NO. SECTION OR BLOCK NO.

D. W

House ( ) Mobile Home (✓) Business ( ) Other


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable-PS Yes (✓) No ( )

Character & Porosity of Soil clay
Percolation Rate Nor
Topography 4-6%
Depth to Water Table 4'+
Rock or other impervious formations none obs.

Lot Area 5.89 Ac.

___ Basement with Plumbing ___ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 4
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓ Existing)
Public ( )

Installed by

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Daniel M. Gibby

IMPROVEMENTS PERMIT BY David R. Hanson, R.S.

COMMENTS: Follow contour with drainfield. No lines deeper than 36" to trench bottom.

CERTIFICATE OF COMPLETION BY DATE

EXISTING SYSTEM CHECKED BY: DAT

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGU

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's C