DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #:
COUNTY:

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Beverly Pierce APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3/-
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: _____ PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | | 0-6" | Brw SCL | | | | | | PS .3 |
| | | 6"-24" | Brw C/C w/few to many SAP Inclus | | | S-SS, SPSE FI-FR | | | |
| | | 24-36" | Rd/Brw C/C w/lots of SAP Inclus & common Mica Flakes | | | SS, SPSE, FR | | | |
| | | 36-48" | SL/L SAP | | | | | | |
| 2 | | 0-30" | Rd/Brw C/C w/ Yellow Mottles | | | | | | PS .2 |
| | | 30" | Chroma 2 Mottles | | | | | | |
| 3 | | 0-10" | Brw C mSBK S, PSE FI | | | | | | PS .3 |
| | | 10-36" | Rd/Brw to Brw C/C w/ Many SAP Inclus | wSBK SS, SPSE FR common mica flakes | | | | | |
| | | 36-48" | SL/C SAP | | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____