4674585118 4674588254

13236

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Quinton T Hall DATE 8/23/91 PERMIT NO. IA-A-20C

PHONE: Business _____ Home _____

LOCATION Patterson Rd, 1365 TL on Patterson Rd. w 1/2 mile TL between planters, follow road to barn S. R. No. _____

SUBDIVISION NAME N/A LOT NO. N/A SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No	(✓)
Auto. Dishwasher	Yes (✓)	No	( )
Auto. Wash. Machine	Yes (✓)	No	( )
Site Suitable	Yes (✓)	No	( )

Character & Porosity of Soil clay transition - P - mid/upper/lower
Percolation Rate .35
Topography 2-5%
Depth to Water Table 748"
Rock or other impervious formations COBBLY - MIX FILL + ORIGINAL

Lot Area 20,000 FT²

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 4 @ 90-100
Sq. Ft. 1200 Linear Ft. 400
Depth of Stone in Lines 12"

Water Supply: Individual (✓) FROM FATHERS HOUSE
Public ( )

Installed by Benton Landscaping

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Wesley Sparks RS. DATE 8/23/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

2/800

13236

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Quinton T Hall DATE 8/8/91 PERMIT NO. IR-A-20C

PHONE: Business _____ Home _____

LOCATION Patterson Rd, 1365 TL on Patterson Rd ~ 1/2 mile on TL between planters, follow road to barn S. R. No. _____

SUBDIVISION NAME 14/14 LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms ~~4~~ 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area 20,000 FT²

Character & Porosity of Soil clay transition – P
Percolation Rate .25
Topography 2-5%
Depth to Water Table >48"
Rock or other impervious formations COBBLY – MIX FILL & ORIGINAL

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 4 @ 90-100'
Sq. Ft. 1200 Linear Ft. 400
Depth of Stone in Lines 12"
Water Supply: Individual (✓) FROM FATHERS HOUSE
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Quinton T Hall

IMPROVEMENTS PERMIT BY Wesley Sparks RS.

COMMENTS: Trenches no deeper than 30" to trench bottom. Trenches to start from drop boxes as shown and run in direction shown on contour.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.
Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold