4675105514

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

82
83

OWNER OR CONTRACTOR William McCullen DATE 3-19-85 PERMIT NO.

PHONE: Business Home

LOCATION 1146 S TR 1142 ½ mile TR (before JR River)
Carolwoods Drive lot on R on corner S. R. No.

SUBDIVISION NAME Carolwoods LOT NO. 18, 19, 20, 21 SECTION OR BLOCK NO.


House (X) Mobile Home ( ) Business ( ) Other

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (X)	Character & Porosity of Soil	Clay	
Auto. Dishwasher	Yes (X)	No ( )	Percolation Rate	0.5 gal/ft²/day	
Auto. Wash. Machine	Yes (X)	No ( )	Topography	2-10%	
Site Suitable	Yes (X)	No ( )	Depth to Water Table	4'	
			Rock or other impervious formations	none obs	

Lot Area 20,000 ft²

____ Basement with Plumbing ____ Basement without Plumbing X No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 720 Linear Ft. 240
Depth of Stone in Lines 12"

Water Supply: Individual (X)
Public ( )

Installed by J. R. Bowles

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed:

IMPROVEMENTS PERMIT BY Fred Clemmer

COMMENTS: dam in 1st line 1'+1' too much fall

CERTIFICATE OF COMPLETION BY Charles K. Barnett DATE 3-13-85

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold