4675 81 7913

13599

IREDELL COUNTY HEALTH DEPARTMENT

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR Joseph Stewart DATE 7/22/92 PERMIT NO. Pt. IA-A-12

PHONE: Business _____ Home 692-5532

LOCATION Patterson Farm Rd., 1.5 miles from Cobble Creek on (L) up road to field above old barn. S.R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ☑ Mobile Home ☐ Business ☐ Other _____

No. Bedrooms 3 No. Bathrooms 2.5

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area ~ 10 AC

Soil Characteristics P - C (wk structure, Firm)

Application Rate P .25

Topography P - 2-3%

Depth to Water Table P - 40" To GLEYING

Rock or other impervious formations S - NONE OBSERVED

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement ✓ Crawl Space

Size of Tank 4@ 120' X 3' 1250 Gals.


Nitrification Field:

No. of Lines 4@ 120' X 3'

Sq. Ft. 1440 Linear Ft. 480

Depth of Stone in Lines 12"

Water Supply: Individual ☑ Public ☐



Plot of System (Not to Scale)

Installed by Williams Septic Co

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: _____

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY _____

COMMENTS _____

CERTIFICATE OF COMPLETION BY Wesley Sparks RS. DATE 7/22/92

EXISTING SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

9:30-10:00

IREDELL COUNTY HEALTH DEPARTMENT

13599 (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Joseph Stewart DATE 1/7/92 PERMIT NO PT 1A-A-12

PHONE: Business _____ Home 692-8532

LOCATION Patterson Farm Rd, 1.5 miles from Coddle Creek on (L), up road past barn to house on (R) S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2.5

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area ~10 AC

Character & Porosity of Soil P-C-SiC (wk structure)
Percolation Rate 25
Topography 2-3%
Depth to Water Table 40"
Rock or other impervious formations None found.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

→ 1000 GAL.
Size of Tank 4 @ 120' x 3' Gals.
Nitrification Field:
No. of Lines 4 @ 120' x 3'
Sq. Ft. 1440 Linear Ft. 480
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed Joseph Stewart

IMPROVEMENTS PERMIT BY Wesley Sparks R.S.

COMMENTS: Trenches must be no deeper then 24" to trench bottom. Lines to follow slope contour in the direction shown. Drainfield area may not be plowed over after system is installed.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold