4676105929

# IREDELL COUNTY HEALTH DEPARTMENT

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ronald Barnette ~~MARK RUMMAGE~~ DATE 3/8/88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 136 SOUTH ON LEFT JUST BEFORE JCT. W/ 1199 (Williford Rd.) S. R. No. _____

SUBDIVISION NAME BURL ACRES LOT NO. 1 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes (✓) No ( )
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil Clay ~ 4gpd/ft2
Percolation Rate 4"
Topography 89°
Depth to Water Table 4'+
Rock or other impervious formations none observed

Lot Area _____

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement




Plot of System NOT TO SCALE

Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by LAVADEN BENTON

I understand and agree to install septic tank system as specified on this Improvements Permit.

The proposed / existing Out Building addition does not appear to impact the existing septic system.
**NOTE: Keep Bldg at least 5Ft from Septic & 25Ft from well

Maria Dotson REHS
Date: 4/14/2010
ICHD-Environmental Health Division

IMPROVEMENTS PERMIT BY DRH

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Andrew C. Price DATE 3/8/88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

Co DOLE ERESR. RD