4076245760

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Kent Jewell DATE 4/9/86 PERMIT NO. 139

PHONE: Business _____ Home _____

LOCATION Main St, Rt on Linwood, 1/4 mile past Brumley on Lf

S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other Repair


No. Bedrooms 4 No. Bathrooms 2½

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil _____
Percolation Rate _____
Topography Existing
Depth to Water Table _____
Rock or other impervious formations _____

Lot Area _____

_____ Basement with Plumbing ✓ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank Existing Gals.
Nitrification Field: 2
No. of Lines
Sq. Ft. 360 Linear Ft. 120
Depth of Stone in Lines 12
Water Supply: Individual (✓)
Public ( )

Installed by Wayne Orbison

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Kelly R Sheeks RS

COMMENTS: Layout change OK'D by KS prior to construction.
New lines fed by first from new Tee in Tank.

CERTIFICATE OF COMPLETION BY Kelly R Sheeks RS DATE 4/9/86

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

11:00-11:30
Orbison

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Kent Jewell DATE 4/8/86 PERMIT NO.

PHONE: Business Home

LOCATION Main St, Rt on Linwood, 1/2 mile past Brumley Rd on Lf

S. R. No.

SUBDIVISION NAME LOT NO. SECTION OR BLOCK NO.


House (✓) Mobile Home ( ) Business ( ) Other Repair

No. Bedrooms 4 No. Bathrooms 2 1/2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	EXISTING
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	
			Rock or other Impervious formations	

Lot Area

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank Existing Gals.

Nitrification Field:
No. of Lines 1
Sq. Ft. 360 Linear Ft. 120
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed Kent Jewell

IMPROVEMENTS PERMIT BY Leigh Sheek RS

COMMENTS: Use schedule 40 4" PVC if you attempt to save grapevine.

CERTIFICATE OF COMPLETION BY DATE

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold