IREDELL COUNTY HEALTH DEPARTMENT 4676-26-8226

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ricky Christy DATE 10/30/87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 1150 (Linwood Rd) TL 1153 (Brumley) TR
1st Entrance to Quail Hill. 1/8 mile on Rgt. S. R. No. _____


SUBDIVISION NAME Quail Hill LOT NO. 87 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1-2
Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )
Lot Area 9/10

Character & Porosity of Soil Clayey
Percolation Rate V. Fast gpd / ft²
Topography 15-25%
Depth to Water Table 4'+
Rock or other impervious formations none observed

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 600 Linear Ft. 200
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by Delbert Bostian

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY ACP

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Andie C. Queen DATE 10/30/87

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

P.P. 0137

4:00

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ricky Christy DATE 10/1/87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 1150 (Linwood Road) TL 1153 (BRUMLEY ROAD) TR 1st entrance to Quail Hill 1/8 mile on Right.

SUBDIVISION NAME Quail Hill S. R. No. _____

LOT NO. 87 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1-2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area 9/10 Acre

Character & Porosity of Soil Clayey


Percolation Rate 1.4 gpd/ft²

Topography 15-25%

Depth to Water Table 4'+

Rock or other impervious formations none observed

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System NTS.

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 2

Sq. Ft. 600 Linear Ft. 200

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Neighbor's well.

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Ricky Christy

IMPROVEMENTS PERMIT BY 10 for Andre C Rieux

COMMENTS: Install system SHALLOW (30" to trench bottom). STAY ON GRADE. Use properly installed drop boxes. Call Health Dept for SPECS.

CERTIFICATE OF COMPLETION BY _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold