IREDELL COUNTY HEALTH DEPARTMENT 4676-26-8431

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR PBS Realty DATE 5/27/87 PERMIT NO.

PHONE: Business Home


LOCATION 1150 Lf on Brumley, Rt into 1st Entrance of Qual Hill ≈ 100 yards on Rt S. R. No.

SUBDIVISION NAME Qual Hill LOT NO. 88 SECTION OR BLOCK NO.

House ( ) Mobile Home (✓) Business ( ) Other Doublewide

| | | | | | |
|---|---|---|---|---|---|
| No. Bedrooms 3 | No. Bathrooms 2 | | | Character & Porosity of Soil | Shallow cly trans. to pm |
| Garbage Disposal Unit | Yes ( ) | No (✓) | | Percolation Rate | ≈ 0.4 gpd/ft² |
| Auto. Dishwasher | Yes (✓) | No ( ) | | Topography | 4-10% |
| Auto. Wash. Machine | Yes (✓) | No ( ) | | Depth to Water Table | 4'+ |
| Site Suitable | Yes (✓) | No ( ) | | Rock or other impervious formations | None noted |

Lot Area




Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 900
Depth of Stone in Lines 12"

Water Supply: Individual (✓) To be drilled
Public ( )

Installed by Bellinger Septic Tank

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed:

IMPROVEMENTS PERMIT BY David R. Hinson, RS.

COMMENTS: Keep well 50' minimum from septic area.

CERTIFICATE OF COMPLETION BY DATE 5/27/87

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

1:00
Delivered

# IREDELL COUNTY HEALTH DEPARTMENT

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR P.B.S. Realty DATE 5-20-87 PERMIT NO.

PHONE: Business Home

LOCATION 1150 TL 1153 (Brumley) TR into 1st entrance Quail Hill 100 yds on Lt.

SUBDIVISION NAME Quail Hill S. R. No.

LOT NO. 88 SECTION OR BLOCK NO.

P.W.

House ( ) Mobile Home (✓) Business ( ) Other


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Lot Area ~3/4 AC

Character & Porosity of Soil shallow clay trans. to pm
Percolation Rate 24
Topography 4-10%
Depth to Water Table 48+
Rock or other impervious formations SAP inc w/ depth

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement




Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 4
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by

I understand and agree to install septic tank system as specified on this Improvements Permit.

X Signed:

IMPROVEMENTS PERMIT BY David R. Harrison R.S.

COMMENTS: Drainfield must be installed shallow (12" over max) Use a series of drop boxes to distribute effluent. May be able to use 3 ditches 3'x100'.

CERTIFICATE OF COMPLETION BY

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold