07729

IREDELL COUNTY HEALTH DEPARTMENT

4676-35-2527

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Donald Smith DATE Dec. 31, 87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION N. Main St. TR 1150 (Spruce Rd.) TR 1153 (Brumley Rd.) TR 1st entrance into Quail Hill 1/8-1/4 mile on Rt. S. R. No. _____

SUBDIVISION NAME Quail Hill LOT NO. 82 SECTION OR BLOCK NO. _____

DW

House ( ) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil clay
Percolation Rate ~ 4
Topography 2-4%
Depth to Water Table 4+
Rock or other impervious formations none obs.

Lot Area ~3/4 Ac

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )
Well already drilled

Installed by Owner

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DHH

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Donald R. Hinson, R.S. DATE 12-31-87

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

07729

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Donald Smith DATE Dec 7, '87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION N. Main St. TR Linwood Rd. (1150) TL Brumley Rd. (1153) TR 1st entrance into Quail Hill ⅛-¼ mile on Rt. S. R. No. _____

SUBDIVISION NAME Quail Hill LOT NO. 82 SECTION OR BLOCK NO. _____

D.W.

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil clay

Percolation Rate 2, 4


Topography 2-4%

Depth to Water Table 4'

Rock or other impervious formations none obs.

Lot Area ~3/4 Ac.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 300 Linear Ft. 300

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Well already down

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Donald Smith

IMPROVEMENTS PERMIT BY Gaidel R. Hunsucker R.S.

COMMENTS: Install drainfield at a maximum depth of 30" to bottom of ditch. Follow contour

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold