4676-35-3881

1149S

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ozella Pratt DATE Sept. 30, '91 PERMIT NO. IH-12-A-42

PHONE: Business _____ Home _____

LOCATION 1150 TR 1153 (Brumley) TR 1st entrance into Quail Hill • 2 mile on left S. R. No. _____

SUBDIVISION NAME Quail Hill LOT NO. 42 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site ~~Suitable~~ PS Yes (✓) No ( )

Lot Area 1/2 - 3/4 Ac

Character & Porosity of Soil PS clay


Percolation Rate 4.4 2.49

Topography

Depth to Water Table 41+

Rock or other impervious formations none obs.

Basement with Plumbing ____ Basement without Plumbing ____ No Basement ✓



Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 900 Linear Ft. 300

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by Benny Myers

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY SET

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Thomson, RS DATE 9-30-91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

3-30-92 ?

IREDELL COUNTY HEALTH DEPARTMENT

11495 (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ozella Pratt DATE May 16, 1992 PERMIT NO. LH-12-A-42

PHONE: Business _____ Home _____

LOCATION Linwood TL Brumley TR 1st Drive into Quail Hill Lot 42 On left .2 mi. S. R. No. _____


SUBDIVISION NAME _____ LOT NO. 42 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2
Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes ( ) No ( )
Lot Area ± 3/4 ac

Character & Porosity of Soil b/c @ 36"
Percolation Rate ~ .4 gpd/sft
Topography 1-5%
Depth to Water Table ± 3'
Rock or other impervious formations none obs

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300'
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed Ozella Pratt

IMPROVEMENTS PERMIT BY Sam Ingram EHS

COMMENTS: Front of mobile home should be 110' off edge of road. Right end of trailer should be 30' min. of property line Trench bottom shall be 30" max. depth.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold