IREDELL COUNTY HEALTH DEPARTMENT 4676-36-0182

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Kelly Kenneway DATE 6-27-86 PERMIT NO. 375

PHONE: Business _____ Home _____

LOCATION N. Main TR on Linwood TL on Brumley TR on to 1st Quail Hill enterance ½ mile on left S. R. No. _____

SUBDIVISION NAME Quail Hill LOT NO. 39 SECTION OR BLOCK NO. _____

House ( ) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes ( ) No (✓)
Auto. Wash. Machine Yes ( ) No (✓)
Site Suitable Yes (✓) No ( )

Lot Area 1.36 acres

Character & Porosity of Soil clay / parent material
Percolation Rate 4 gal/sq ft/day
Topography LA 2-4%
Depth to Water Table 4'
Rock or other impervious formations none obs

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by Chapin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Charles K. Barnett

COMMENTS: well is not down yet need to be 50' from tank & lines

CERTIFICATE OF COMPLETION BY Charles K. Barnett DATE 6-27-86

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold