4676-36-2583

10692

# IREDELL COUNTY HEALTH DEPARTMENT

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Benny Lee Saltz DATE Jan. 19 '90 PERMIT NO. IHL-388

PHONE: Business _____ Home _____

LOCATION 1150 TR 1153 (Brumley) TR 1st entrance into Quail Hill 3rd lot on left

S. R. No. _____

SUBDIVISION NAME Quail Hill LOT NO. 38B SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area 2.56 Ac

Character & Porosity of Soil 95 clay


Percolation Rate 4

Topography 6-8% comp slp

Depth to Water Table 4ft

Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement




Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 6 (3+3 w/ flowleveler)

Sq. Ft. 900 Linear Ft. 300

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by Dellinger

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DBH

COMMENTS: Well not drawn.

CERTIFICATE OF COMPLETION BY DB Hinson, RS DATE Jan. 19 '90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

10692

# IREDELL COUNTY HEALTH DEPARTMENT

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Benny Lee Seltz DATE Nov. 989 PERMIT NO. IHL 388

PHONE: Business _____ Home _____

LOCATION 1150 TR 1153 (Brumley) TR 1 5th entrance into Quail Hill 4th lot on left S. R. No. _____

SUBDIVISION NAME Quail Hill LOT NO. 38B SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site ~~Suitable~~ S Yes ( ) No ( )

Lot Area 2.56 Ac

Character & Porosity of Soil clay


Percolation Rate 2.4

Topography 6-8% Complex

Depth to Water Table 4+

Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ___/___ No Basement




Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 6

Sq. Ft. 900 Linear Ft. 300

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Complex

15' Topo

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: X Benny L. Seltz

IMPROVEMENTS PERMIT BY David R. Henson, L.S.

COMMENTS: Pull plumbing out at upper end of mobile home at ground level. Follow contour with drainfield and install lines at a depth of 24"to 30" trench bottom. Split flow from tank with flow divider and go to two "mini fields" of 150' in 3 fifty foot trenches.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold