IREDELL COUNTY HEALTH DEPARTMENT 4676-36-6286

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Voigt Barnhart DATE Aug. 3, 1988 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION LINWOOD TL BEUMLEY TR QUAIL HILL TL @ STOP SIGN . ON Left. S. R. No. _____

SUBDIVISION NAME Quail Hill. LOT NO. 51A SECTION OR BLOCK NO. _____


House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Clayey
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	.4
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-6%
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	4'+
			Rock or other impervious formations	none

Lot Area _____

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System NOT TO SCALE

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (X)
Public ( )

Installed by Dellinger Grading LINCOLNTON

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY A.C.P.

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Andrew C. Pruitt DATE Aug 3, 1988

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

06685

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR P.B.S. Realty (Voigt Barnhardt) DATE 7/26/88 PERMIT NO. _____

PHONE: Business _____ Home 525-4848

LOCATION Linwood TL Brumley TR Quail Hill TL on L.

SUBDIVISION NAME Quail Hill LOT NO. 52 A SECTION OR BLOCK NO. _____ S. R. No. _____

House ( ) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2 1

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil Clayey
Percolation Rate 4
Topography Gently
Depth to Water Table 4'+
Rock or other impervious formations none observed

Lot Area 3/4 ACRE

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 960 Linear Ft. 320
Depth of Stone in Lines 12"
Water Supply: Individual ✓
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed J W M Barnhardt

IMPROVEMENTS PERMIT BY Andrew C. Brun

COMMENTS: Install shallow system. Use Sch. 40 PVC pipe 4" to plumb system (at least 2" out to working lines). Use 4 drop boxes and keep system shallow and level.

CERTIFICATE OF COMPLETION BY _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS. DATE _____

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold