4676-36-8475

11764

# IREDELL COUNTY HEALTH DEPARTMENT

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR PBS Realty DATE Oct. 17, '91 PERMIT NO. 1H-12-A-53454

PHONE: Business _____ Home _____

LOCATION 1150 TR 1153 TR 1st entrance into Quail Hill TL @ Stop Sign 1st rd to right at end S. R. No. _____

SUBDIVISION NAME Quail Hill LOT NO. 53454 combined SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site ~~Suitable~~ PS Yes (✓) No ( )

Lot Area ~5 Ac

Character & Porosity of Soil ps clay trans


Percolation Rate n.t.

Topography 6-10%

Depth to Water Table 6'+

Rock or other impervious formations saprolite w/ depth very well weathered

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement




Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 900 Linear Ft. 300

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by Ken Dellinger

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH

COMMENTS: Well not installed as of this date.

CERTIFICATE OF COMPLETION BY David R. Hinson, RS DATE 10-17-91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

11764

# IREDELL COUNTY HEALTH DEPARTMENT

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR PBS Realty DATE Aug 22, '90 PERMIT NO. IH-12-A-5345

PHONE: Business _____ Home _____

LOCATION 1150 TL 1153 (Brumley) TR 1st entrance into Quail Hill to Stop sign TL TR 1st Street at end S. R. No. _____

SUBDIVISION NAME Quail Hill LOT NO. 53 & 54 combined SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area ~5 Ac.

Character & Porosity of Soil shallow 15 clay loam.


Percolation Rate ~ 24

Topography 6-10% 4 ft

Depth to Water Table _____

Rock or other impervious formations Saprolite increasing with depth

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement




Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines ~3-4

Sq. Ft. 900 Linear Ft. 300

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: James T. Barkley

IMPROVEMENTS PERMIT BY DR Hinson, EHS

COMMENTS: Follow contour with drainfield. Maximum trench bottom depth 24".

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold