Craig Freeze 4676-37-2081 [redacted]

06723

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Robert Rhyne DATE Dec. 7 '89 PERMIT NO. IG-H-56

PHONE: Business _____ Home _____

LOCATION 150 E Bear Right on 152 (towards China Grove) 202 Brumley TR 1153 (Brumley Rd.) 2 1/4-1/2 mile on Right S. R. No. _____

SUBDIVISION NAME Elmore property LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes (✓) No ( )
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site ~~Suitable~~ PS Yes (✓) No ( )
Lot Area 5.4 Ac

Character & Porosity of Soil clay
Percolation Rate n.t
Topography 2-4%
Depth to Water Table 6'+
Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓) Public ( )

Installed by George Moss

I understand and agree to install septic tank ts

The proposed Trophy Room addition does not appear to impact the existing septic system.
**NOTE: _____

Marina Dobson R.S.
Date: 2-27-09
ICHD-Environmental Health Division

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY _____ DATE 2-7-89

EXISTING ~~SYSTEM~~ CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.
Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.