IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Michael Wilkie DATE 4-23-86 PERMIT NO. 201

PHONE: Business _____ Home _____

LOCATION Fairwood Rd T.L. on Brumley 2nd Entrance To Quail Hill corner of Quail Hill & Lakewind Drive S. R. No. _____

SUBDIVISION NAME Quail Hill LOT NO. 24 SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Clay loam / Clay
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	5
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2 to 4%
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	4' +
			Rock or other impervious formations	none

Lot Area 1 acre

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 720 Linear Ft. 240
Depth of Stone in Lines 12

Water Supply: Individual (✓)
Public ( )

Installed by Kenneth Chaffin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Kelly Sheeks

COMMENTS: _____

CERTIFICATE OF COMPLETION BY R. C. Moore DATE 4-27-86

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Michael Wilkie DATE 3/4/86 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Linwood Road LF on Brumley Rt in 2nd Entrance of Quail Hill, Corner of Quail Hill & Rakewind Drive S. R. No. _____


SUBDIVISION NAME Quail Hill LOT NO. 24 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil clay loam / clay
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate 0.5 apt/ft
Auto. Wash. Machine	Yes (✓)	No ( )	Topography 2-4%
Site Suitable	Yes (✓)	No ( )	Depth to Water Table 4'+
Lot Area 1 acre			Rock or other impervious formations None Noted

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 720 Linear Ft. 240
Depth of Stone in Lines 12

Water Supply: Individual (✓) To be drilled
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Barbara Wilkie

IMPROVEMENTS PERMIT BY Kelly Sheets RS

COMMENTS: Keep well 50' from septic area.

CERTIFICATE OF COMPLETION BY _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold