DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Jacob Compton
ADDRESS: _____ APPLICATION DATE _____
DATE EVALUATED: 11-6-06
PROPOSED FACILITY: MH PROPOSED DESIGN FLOW (.1949): 360gpd
PROPERTY SIZE: _____
LOCATION OF SITE: Teeter Rd across from 456
PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941)		OTHER PROFILE FACTORS				PROFILE CLASS & LTAR
			.1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	.1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	
1	linear sideslope 5%	0-8	lsbk cl			48			PS .3
		8-34	lsbk c	fr ss/sps se					
		34-40	lsbk cl	fr					
		40-48	cl + s/sap						
2		0-4	lsbk sl			48			PS .3
		4-30	lsbk c	fr/fi ss/sps se					
		30-48	lsbk cl	fr					
3	Repair area field	3-0	fill? from tree hole			48			PS .3
		0-30	lsbk c	fi ss/sps se					
		30-48	lsbk cl	fr					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	yes	yes
System Type(s)	26% grav	Sand
Site LTAR	.3	.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: J. Melville
OTHER(S) PRESENT: J. compton

COMMENTS: