DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET___OF___
PROPERTY I.D.#:
PROPERTY RECORDED:
COUNTY:

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: EDWARD DGIEN OWNER:X AGENT:__ PHONE: 634-5367
ADDRESS: APPLICATION DATE: 11/1 DATE EVALUATED: 11-22-00
PROPOSED FACILITY: 3BD - 3BA CRAWL
PROPERTY SIZE: 1.00
LOCATION OF SITE: ~~Serene Lake Subdiv. Lot 5~~ Lot 6 Magnolia Ridge
WATER SUPPLY: On-Site Well X Comm. Well__ Public___ Other_____ EVAL. METHOD: Auger__ Boring__ X Pit__ Cut___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	~CC	0-4	MM SBK / CL	FR SS SP					
		5-11	MS SBK / C	FI S P					
		12-26	MS ~ABK / C SAP	SEXP FI S P					.2
		27-	U			ROCK			
2	~CC	0-3	MF SBK / SCL	FR S SP					
		4-13	MS SBK / C	SEXP FI S P					
		14-21	SM ~ABK / C SAP	SEXP VFI SS P	F. MOT				
		22	U			VFI SAP			.25
3	T CC L	0-8	GR / S	VFR NP NS					
		9-17	MM SBK / CL	FI S SP					
		18-29	MS SBK / C	FR SS SP	F MOT <5%			↓PS	
		30-39	MF SBK / C SAP	SEXP FI S P				U	.25
4	3-4 LS	0-6	M SBK / CL	FR SS SP					
		7-15	MF SBK / CL SAP	FR SS SP				PS	
		16-42	F SBK / L SAP	VFR SS NP					.3
		43-49	MF GR / L SAP	VFR SS NP					.3
5									

AVAILABLE SPACE (.1945) U SITE CLASSIFICATION (.1948): U SITE LONG-TERM ACCEPTANCE RATE:
EVALUATED BY: Sparks OTHER(S) PRESENT: Dgien (Dan)
COMMENTS: May move to lot 7 instead - Lot 6 will require backhoe pits