DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Michael Maher APPLICANT: _____
ADDRESS: Teeter Rd APPLICATION DATE: _____ DATE EVALUATED: 12/12/97
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: _____ PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ	PROFILE CLASS & LTAR
5/1		0-4"	Brw SL GR FR						
		4-18"	Rd/Brw LtC/C Hearth	SBK SS,SP,SE,FI-FR					
		18"-48"	Rd/Brw C/Cl	SBK SS,SP,SE,FI		Chroma 2 Mottles at 18			U
6/2		0-4"	Brw SCL GR FR						
		4-20"	Rd-Brw C/Cl	SBK SS,SP,SE,FI-FR					
		20-42"	Rd-Brw SC	S,P,E, FR	Chroma 2 Mottles				
		42"-48"	Rd/Brw C/Cl	SBK SS,SP,SE, FR	w/ 20"		Fluctuation		
7/3		0-6"	Brw SCL GR FR						
		6"-24"	Rd/Brw SBK C	S,P,E,FI	Chroma 2 Mottles at 20"				
		24"-48	Rd/Brw C/Cl	SBK w/SAP					
			Increasing Rock Fragments						
4/4		0-6"	Brw SCL GR						
		6"-48"	Rd/Brw SBK C/Cl	S,P,FI-SE	Chroma 2 Mottles				
		18"-36"	Rd/Brw SC/C	S,P,FI-SE	w/ Rock Fragments				
		36"-48"	Rd/Brw C/Cl	SS,SP,SE, FR w/SAP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____