8154

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Robert Yearington DATE April 7, 88 PERMIT NO.

PHONE: Business Home

LOCATION 150 E. TL just past Carrigan Farms rear end on left

SUBDIVISION NAME Oakmeadow LOT NO. 10 SECTION OR BLOCK NO. S. R. No.

House (✓) Mobile Home ( ) Business ( ) Other

No. Bedrooms 3 No. Bathrooms 2


Garbage Disposal Unit	Yes	(✓)	No	( )
Auto. Dishwasher	Yes	(✓)	No	( )
Auto. Wash. Machine	Yes	(✓)	No	( )
Site ~~Suitable~~ PS	Yes	(✓)	No	( )

Lot Area ½ Ac+

Character & Porosity of Soil clay CLASS IV
Percolation Rate 12-31
Topography 4-8%
Depth to Water Table 4ft
Rock or other impervious formations Abd of scattered rock

✓ Basement with Plumbing ____ Basement without Plumbing ____ No Basement

1250 gal pump tank



Plot of System

Size of Tank 1250 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. ____ Linear Ft. 270 of 16"
Depth of Stone in Lines 24" gravel
Water Supply: Individual (✓) pressure dosed
Public ( )

Installed by

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Donna R. Yelton

IMPROVEMENTS PERMIT BY David R. Hinson

COMMENTS: Drainfield installed prior to issuance of permit because of rock problems (270' of LP panels, one 3/16" hole/panel)

CERTIFICATE OF COMPLETION BY

SYSTEM CHECKED BY: DATE

DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.
is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making ements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold