DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

76.3477
534.0 42 539

OWNER: Doug Adams
ADDRESS: _____
APPLICANT: _____
APPLICATION DATE: _____
DATE EVALUATED: 1/13/?
PROPOSED FACILITY: _____
PROPOSED DESIGN FLOW (.1949): _____
PROPERTY SIZE: _____
LOCATION OF SITE: _____
PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | 1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE | 1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR | 1943 SOIL DEPTH | 1956 SAPRO CLASS | 1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | LL 10-15% | 0-4" | Brw SCL GR | FR | | | | | PS .3 |
| | | 4"-28" | Rd Brw Hvy CL | mSBK SS,SP,SE FI-FR | | | | | |
| | | 28-48" | Rd/Brw CL | FSBK SS,SP,SE FR | | | | | |
| | | | w/ Indus of SAP | | | | | | |
| 2 | LL 12% | 0-5" | SCL GR | FR | | | | | PS .3 |
| | | 5-34" | Rd/Brw C/CL | FI <-SP,SE,FI-FR w/ Indus of Rock Fragments & Common Mica Flakes | | | | | |
| | | 34-48" | Rd/Brw CL w/SAP & Rock Fragments | w/Common Mica Flakes in clus | | | | | |
| 3 | LL 10% | 0-5" | SCL GR | R | | | | | PS .3 |
| | | 5"-40" | Rd/Brw CL | mFSBK SS,SP,SE FI-FR | | | | | |
| | | | w/ Weather Rock Indus & Common Mica Flakes | | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____