11751

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Marcus Jones DATE 7/18/90 PERMIT NO. IG-A-52

PHONE: Business _____ Home _____

LOCATION 152 E TR Brumley 2nd drive on left

_____ S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____ Area of drainfield

No. Bedrooms	3	No. Bathrooms	2½	Character & Porosity of Soil	PS clay
Garbage Disposal Unit	Yes ( )	No (✓)		Percolation Rate	No. 3 and 4
Auto. Dishwasher	Yes (✓)	No ( )		Topography	Lay 1 5.10%
Auto. Wash. Machine	Yes (✓)	No ( )		Depth to Water Table	none +3'
Site Suitable PS	Yes (✓)	No ( )		Rock or other impervious formations	none obs


Lot Area 11.85 ac

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement

1000PT

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 7-8
Sq. Ft 1200 Linear Ft. 400'
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )



Plot of System

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Marcus A. Jones

IMPROVEMENTS PERMIT BY Sam Ingram EHS

COMMENTS: 270' Sch 40 Supply Line 2"
32 gpm pump 24' TDH 1 Hole 5/32" every 5 feet
1¼" lateral

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold