DIVISION OF ENVIRONMENTAL HEALTH:
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Susan Pack APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 12/1/99
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Teeter Rd PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-4	Top Soil		Many SAP Indus		Need to Evaluate SAP in Back hoe Pits		
		4-18"	Brn C w/ SL/L	SAP					
		18-48							
2		0-7"	Top Soil / Brn C/Cc						
		7-36"	SL/L	SAP					
3	toward Rd	0-5	Top Soil		mu SBK SS, SP Indus many SAP		FI-FR w/ few to		PS, 3 to 34"
		5-34	Brn to Rd/Brn C/Cc						
		34-48"	Brn C/Cc + SAP mix						
4	Very close to Rd	0-34"	Brn to Rd/Brn C/Cc		m-mu SBK SS, SP w/ few to		FI-FR many SAP Indus		PS, 3
		34-48	Brn C/Cc + SAP mix						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____