IREDELL COUNTY HEALTH DEPARTMENT

APPENDIX H

SITE EVALUATION

(Ground Absorption Sewage Disposal)

OWNER: Ernest Chambers DATE REQUESTED: 1-9-81

ADDRESS: PLAT NO.:

COUNTY: Iredell LOT SIZE: 4 Acre

LOCATION OF SITE: 152E past jct with 152E splits off ½ mile our before County Line

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) U 2-4%	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 clay)	S (PS) U clay	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey soils)	S (PS) U Subangular	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) PS U 48"	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	(S) (PS) U None observed	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	S (PS) U Mottles	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS U 80-100 mpi	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION*	PS			
SOIL SERIES	Cecil			

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments:

Described By: MK

Title: S-T Date: 1-9-81

DHS Form 2601 (2/77)
Sanitation