Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet: 1 OF 1
PIN #: 4679-19-2745
Lot #:
Permit #: 201839
AppID:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: BRYAN CLODFELTTER
Applicant: SAME
Address: 1824 TRIPLETT RD.
Date Evaluated: 4/4/2014
Proposed Facility: SFR
Design Flow (.1949) 480
Property Size: 1 AC
Location of Site: SAME
Property Recorded:
Water Supply: [ ] Public [X] Individual [X] Well [ ] Spring [ ] Other
Evaluation Method: [X] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Texture	.1941 Consistence Mineralogy	b PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
AB 1	LINEAR 6%	0-20	SCL,W,SBK	FR,SS	NA	40"	S	48+	.35
		20-40	SC,M,SBK	FR,SS					
		40-48	SLSAP	FR,SS					
AB 2	LINEAR 6%	0-26	SC,M,SBK	FR,SS	NA	36"	S	48+	.35
		26-36	SCL,W,SBK	FR,SS					
		36-48	SLSAP	FR,SS					

Description	Initial System	Repair System
Available Space (.1945)		PS
System Type(s)		G-25% RED
Site LTAR		.35

Other Factors (.1946):

Soil Evaluation By: SHANE CASHION

Others Present: BEN ALDRIDGE, BRYAN CLODFELTTER

Site Classification (.1948): PS

Site Evaluation By: SHANE CASHION

Others Present: BEN ALDRIDGE, BRYAN CLODFELTTER