DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Kerri LLC
ADDRESS: _____ APPLICATION DATE _____
PROPOSED FACILITY: Res PROPOSED DESIGN FLOW (.1949): 480 DATE EVALUATED: _____
LOCATION OF SITE: Lot 9 Kerri Subdivision PROPERTY SIZE: _____
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
A1	LSS 5-10%	0-8	BSCL VAR	fri SSSPSap					PS .3
		8-28	RC SAM	fri SSSPSap					
		28-54	RCL WSAM	fri SSSPSap		54	—	—	
				Common SAP	—				
				+ felspar					
B2		0-4	BSCL VAR	fri SSSPSap					PS .3
		4-26	RC SAM	fri SSSPSap					
		26-58	RCL WSAM	fri SSSPSap		58	—	—	
				Common SAP	—				
				+ felspar					
C1		0-30	RC SAM	fri SSSPSap					PS .3
		30-50	RCL WSAM	fri SSSP Sap					
				Common/Many SAP	—	50	—	—	
C7A		0-24	RC MFSAM	fri SSSP Sap					PS .3
		24-48	RCL WSAM	fri SSSPSap					
				Many SAP Inc.	—	48	—	—	

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	—	—
System Type(s)	PPBPS ~~PPBPS~~	PPBPS
Site LTAR	.3	.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Rollans Soil & Env.
OTHER(S) PRESENT: _____

COMMENTS: _____