DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: George Wenig
ADDRESS: ___ APPLICANT: ___
PROPOSED FACILITY: ___ APPLICATION DATE: ___ DATE EVALUATED: ___
LOCATION OF SITE: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___ PROPERTY RECORDED: ___
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | 1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | #1 | 0-18 | CL, SBK, Fr | | | | | | .2 |
| | | 18-32 | C, ABK/SBK, F/Fr, Mods | | | | | | |
| | | 32-42 | CL, SBK, F/Fr, SAP/WR, Mods | | | | | | |
| | | 42-48 | SAP | | | | | | |
| | | | | | | | | | |
| 2 | #2 | 0-18 | CL, SBK, Fr, Moist | | Water Pocket @ 43 | | | | .2 |
| | | 18-32 | C, SBK, F/Fr, Mods | | | | | | |
| | | 32-42 | CL, SBK, F/Fr, Mods, WR/SAP | | | | | | |
| | | 42-96 | SAP | | | | | | |
| | | | | | | | | | |
| 3 | #3 | 0-8 | CL, SBK, Fr | | | | | | .3 |
| | | 8-32 | C, SBK, F/Fr, Mods | | | | | | |
| | | 32-44 | CL, SBK, Fr, WR/SAP | | | | | | |
| | | 44-48 | SAP | | | | | | |
| | | | | | | | | | |
| 4 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___