DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Daniel Duncan
APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: 3BR House PROPOSED DESIGN FLOW (.1949): 360 DATE EVALUATED: 11/5/03
LOCATION OF SITE: W Johnson Rd. PROPERTY SIZE: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other PROPERTY RECORDED: _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	T TERRACE 2-6% ESMT AREA	0-9	sbk / cl BR	FR ss-NP					.2
		9-27	wk sbk / c SAP	FR S-SP					
		27-34	m sbk / sc YR	FR SS-SP					
2	IRR. LS 6-10%	0-9	wk / sc l	FR S-SP	W/PS	W	W		
		9-27	M / c SAP YR,	~2.5Y 5/2 FRENCH VFI S-VP					
3	IRR LS 9	0-5	mwk / c	FR S-P					
		5-30	M AB / c SAP	VFI S-P					
		31	M / c	VFI S-EP	W/PS	W	W S-P		
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	ON W LOT	
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Mark / Daniel Duncan
OTHER(S) PRESENT: _____

COMMENTS: Investigation use of terrace area to (L) of house location on Father's property. To acquire plat showing additional area for drainfield.