DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: Dodd

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: ___ APPLICANT: Oakwood Homes
ADDRESS: 1042 CLN Lotte Hwy Trenton APPLICATION DATE: 12/15/99 DATE EVALUATED: Dec 15 99
PROPOSED FACILITY: SR Non Res PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: 1 Ac
LOCATION OF SITE: Old NC Rd 5th (R) Clayton, (L) Eaton (R) Sarboro on Right PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 2-3%	0-6	GR Plow SC						PS .3
		6-36	SAB C	FR					
		36-48	SAB C SAP Inclusion	FR					
2	R 5-8%	0-6	GR Plow SC						U
		6-22	SAB C	FR					
		24-28	C/SAP MIXED	VFR					
		28+	WTH ROCK						
3	N 3-5%	0-6	Plow GR SC						PS .3
		6-36	SAB C	FR					
		36-40	SAB C/SAP mix	FR VFR					
		40+	SAP	VFR					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	✓	✓
System Type(s)	Conv Bottom	Conv Bottom
Site LTAR	.5	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Joe Potter
OTHER(S) PRESENT: Billy McNeely