DEPARTMENT OF ENVIRONMENTAL HEALTH
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Dawn ~~Warlick~~ Wallick APPLICANT: Piedmont Housing
ADDRESS: 188 Clements Rd Statesville APPLICATION DATE: _____ DATE EVALUATED: 3 22 99
PROPOSED FACILITY: 3 Bd/Rm PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: 2+Ac
LOCATION OF SITE: Lot 47 Lansdowne Estate Rd. PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL. CLASS & LTAR
1	L 10%	0-24	SBK C	FR					PS .3
		24 38	SBK SCL	FR					
		38 46	SBK SCL	FR					
		46+	WPK						
2	L 8-10%	0 18	SBK C	FR					U
		18 24	SBK SCL	FR					
		24+	WPK						
3	L 8-10%	0-18	SBK SC	FR					PS .3
		18 36	SBK SCL	FR					
		36+	SBK SCL	FR					
		48+	WPK/Rock						
4	L 10% A	0-18	SBK SC	FR					PS .3
		18 24	SBK SCL	FR					
		24	Rock						
	B	0 18	SBK SC	FR					
		18 48	SBK SCL	FR					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	1200 sq ft	1200 sq ft
System Type(s)	IIA	IIA/Pump
Site LTAR	.3	.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: [signature] Potter
OTHER(S) PRESENT: _____