DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____
4702 748724

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRYSTAL CLAYTON — APPLICANT: SAME
ADDRESS: P.O. BOX 768, HUNTERSVILLE — APPLICATION DATE: _____ — DATE EVALUATED: 10-31-98
PROPOSED FACILITY: 3BR MH — PROPOSED DESIGN FLOW (.1949): 360 — PROPERTY SIZE: 2.0 ACRES
LOCATION OF SITE: LANSDOWNE #48 — PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAR
1	L	0-20	SBK / CL	FR / NEXP		4		—	4
		20+	ROCK						
2	N	0-18	SBK / CL	FR / NEXP		4			4
		18+	ROCK						
3	H	0-22	SBK / CL	FR / NEXP		4			4
		22+	ROCK						
4	L	0-39	SBK / CL	FR-FI / NEXP		PS	PS		PS 0.3
		39-48	SAPROLITE						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	S	S
System Type(s)	II	II
Site LTAR	0.3	0.3

OTHER FACTORS (.1946): NONE
SITE CLASSIFICATION (.1948): P.S.
EVALUATED BY: S. HEDRICK
OTHER(S) PRESENT: _____