DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: ____
COUNTY: Pinellas

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

APPLICANT: Kings Forest
OWNER: _____ APPLICATION DATE: 8 30 99 DATE EVALUATED: 8.30 99
ADDRESS: _____
PROPOSED FACILITY: 3 Bdrm Dwl PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: _____
LOCATION OF SITE: Lot 11 Lancelot Old Mt Rd South (R) Clow's Ferry (L) Eagle Rd PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other (L) Bethany Dr on left
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL. CLASS & LTAR
1	L 12%	0-18	SBK C SAP Inclusions	FR					
		18-31	SBK C SAP Weathered Rock	VFR-FR					
		31	Wthrd Rock						
2	L 15%	0-20	SBK C SAP Inclusions	VFR					
		20-24	SBK C SAP mar	VFR FR					
		24-34	GR % Wthrd Rock/SAP	VFR					
		34+	Wthrd Rock						
3	L 15%	0-12	Wthrd Rock/SAP						
		12+	Wthrd Rock						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____