1051.

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR 74 PROPERTIES, INC. DATE 4-20-90 PERMIT NO 8H-4-B-34.

PHONE: Business _____ Home _____

LOCATION Hwy 70W - 3 miles past Mt. Valley Rd. - L into dev. - bear Rt. past fork - 1st L - 1st lot on left - cul-de-sac S. R. No. _____

SUBDIVISION NAME WINDFOREST DEV. SECT III LOT NO. 34 SECTION OR BLOCK NO. _____

House ( ) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No ( )
Auto. Dishwasher Yes ( ) No ( )
Auto. Wash. Machine Yes ( ) No ( )
Site Suitable Yes ( ) No ( )

Character & Porosity of Soil Loam Suitable
Percolation Rate 60 Min/Inch
Topography Gently Rolling
Depth to Water Table 72+
Rock or other impervious formations scattered rock

Lot Area 1.34 acres.

_____ Basement with Plumbing _____ Basement without Plumbing ____ No Basement



Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 300 Lineal Ft. 300
Depth of Stone in Lines 1'
Water Supply: Individual ( )
Public ( )

Installed by Dellinger Grading

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Steve Brown

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Steve Brown DATE 5-21-90.

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold