07608

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR ROBERT TARCHALA DATE 9-27-88 PERMIT NO. 13B

PHONE: Business _____ Home _____

LOCATION Hwy 64-W west 4 corners. Two miles past Whitehall Lake on (L) left - Entrance - last Dirt drive - 2nd left on (R) up on hill. S. R. No. _____


SUBDIVISION NAME WINDFOREST DEV. LOT NO. 7 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Prev. Suitable.	
Auto. Dishwasher	Yes ( )	No (✓)	Percolation Rate	4 gal. per sq. ft.	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	1-6%	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	10"+	
Lot Area Ample.			Rock or other impervious formations	scattered rock.	

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field: ✓

No. of Lines 6

Sq. Ft. 600 Linear Ft. 200

Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by Donald Lackey

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Steve Brown

COMMENTS: Well on easter lot.

CERTIFICATE OF COMPLETION BY Steve Brown DATE 9-27-88.

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold