1047.

36827

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR JOSEPH & SUSAN LOWE DATE 4-17-90 PERMIT NO. 8H-4-A-24

PHONE: Business _____ Home _____

LOCATION Hunt 70 W 2 miles past Wilson's Lake - T.L. into dev. & stay left & start down hill near end on left. S. R. No. _____


SUBDIVISION NAME WINDFOREST DEV. LOT NO. 24 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Prev. Suitable	
Auto. Dishwasher	Yes ( )	No (✓)	Percolation Rate	4 MPI @ 12"	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	Gently Rolling	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	10'+	
Lot Area Ample			Rock or other impervious formations	scattered rock	

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by Clarkie Bryce

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Steve Brown

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Steve Brown DATE 5-17-90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold