11372.

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR BOB HARTNESS DATE 5-9-90 PERMIT NO. IC-4-C-1011.

PHONE: Business _____ Home _____

LOCATION Hwy 70 W - 1/2 mi. past Wilkins Oak Dr. T.L. on Shady Rest Rd. - T.R. on Sugar Loaf - 1/4 mi. on left S. R. No. *

SUBDIVISION NAME SANDY REST ACRES LOT NO. 10 + 11 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1.5

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes ( ) No (✓)

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Character & Porosity of Soil Appr. Suitable

Percolation Rate 2-30 Lpg. ft.

Topography 2-B, 2-F

Depth to Water Table 18+

Rock or other impervious formations None observed

Lot Area 4+ Ac.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement

Size of Tank 1000 Gals.

Nitrification Field:


No. of Lines 2

Sq. Ft. per Ft. 120 Lines Ft. 240

Depth of Stone in Lines 11"

Water Supply: Individual (✓)

Public ( )



Plot of System

Installed by James Hudler

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Steve Brown

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Steve Brown DATE 5-9-90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold