# SOIL/SITE EVALUATION
## FOR
## ON-SITE WASTEWATER SYSTEM

APPLICANT: Phillip church OWNER: AGENT: PHONE:
ADDRESS: APPLICATION DATE: DATE EVALUATED:
PROPOSED FACILITY:
PROPERTY SIZE:
LOCATION OF SITE:
WATER SUPPLY: On-Site Well ___ Comm. Well ___ Public ___ Other: EVAL. METHOD: Auger Boring ___ Pit ___ C

| PROFILE # | 1943 LANDSCAPE POSITION | HORIZON DEPTH (IN.) | 1951 STRUCTURE/TEXTURE | 1951 MINERALOGY/ CONSISTENCE | 1951 WETNESS COND. | 1944 'RESTRICT' HORIZONS | 1948 CLASS OF HORIZ | 1937/ 1955 'SAPRLT' CLASS. | HORIZ LT. |
|---|---|---|---|---|---|---|---|---|---|
| 1 | linear 9% | 0 to 8 | L GY | | | | | | |
| | | 8 to 36 | C A1B( SEAP S 10 | | ab Chroma 3 at 36" | | | | 125 |
| 2 | linear 10% | | same | | | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |
| 5 | | | | | | | | | |

AVAILABLE SPACE (1945): yes CLASSIFICATION (1948): P5 SITE LONG TERM ACCEPTANCE RATE: 125
EVALUATED BY: P.C. Moore OTHER(S) PRESENT:
COMMENTS:

000136