DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: Granville

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: ___ APPLICANT: Jerry Price
ADDRESS: ___ APPLICATION DATE: 2-18 2000 DATE EVALUATED: 3-2-2000
PROPOSED FACILITY: 3Bd Rm House PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: .85 Ac
LOCATION OF SITE: Lot 1 Three Oaks Old Hwd 56 (R) Clay Rosey (R) Three Oaks PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other 2nd on Lot
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 3.5%	0-18	SL C						PS .3
		18-34	SCL C Sgrvl						
		34-48	Sgr Z-SL						
2	L 3.5%	0-26	SaL C						PS .3
		26-40	SaL C Sgrvl						
		40+	Sgr						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	✓	✓
System Type(s)	Gravity Conv	25% Red Trench
Site LTAR	.3	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: [illegible]
OTHER(S) PRESENT: ___