04947

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR JACK CLANTON DATE 7-2-86. PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Beulah Church Rd. off Old Mtn. Rd. - T.L. on Mock Mill Rd. - 3/8 mi. on left. S. R. No. _____


SUBDIVISION NAME MOCK MILL RUN LOT NO. 7 29445 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2	No. Bathrooms 1-2	Character & Porosity of Soil	Prop. Suitable.
Garbage Disposal Unit	Yes ( ) No (✓)	Percolation Rate	5 gal./sq. ft.
Auto. Dishwasher	Yes ( ) No (✓)	Topography	2-6%
Auto. Wash. Machine	Yes (✓) No ( )	Depth to Water Table	10'+
Site Suitable	Yes (✓) No ( )	Rock or other impervious formations	none observed.

Lot Area Ample

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 720 Linear Ft. 240
Depth of Stone in Lines 12"

Water Supply: Individual ( )
Public (✓)

Installed by Dennis Gilliker

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Steve Brown

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Steve Brown DATE 7-2-86.

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold