1119.

IREDELL COUNTY HEALTH DEPARTMENT

7676B

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

DATE 3-1-90. PERMIT NO. BM-A-76+76B.

OWNER OR CONTRACTOR ZIMMER USA INC.

PHONE: Business _____ Home _____ S. R. No. _____

LOCATION Old Mt. Pl. west of 7+40W - ½ mi. on left

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

From S 20 & entrance in addition to warehouse loading dock.

House ( ) Mobile Home ( ) Business (✓) Other Addition to EXISTING SEPTIC

No. Bedrooms — No. Bathrooms 1 — Character & Porosity of Soil _____

Garbage Disposal Unit Yes ( ) No (✓) Percolation Rate _____

Auto. Dishwasher Yes ( ) No (✓) Topography _____

Auto. Wash. Machine Yes ( ) No (✓) Depth to Water Table TANK SYSTEM.

Site Suitable Yes (✓) No ( ) Rock or other impervious formations _____

Lot Area EXISTING. ___ No Basement

___ Basement with Plumbing ___ Basement without Plumbing

Size of Tank EXISTING Gals.


Nitrification Field:

No. of Lines _____

Sq. Ft. _____ Linear Ft. _____

Depth of Stone in Lines _____

Water Supply: Individual ( )
Public (✓)



Plot of System

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____ DATE _____

COMMENTS: Existing septic tank system functioning properly at the time of inspection.

CERTIFICATE OF COMPLETION BY Steve Brown DATE 3-1-90.

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold