DEPARTMENT OF ENVIRONMENT,
HEALTH & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

DRAFT

SHEET 1 OF 1
PROPERTY I.D.#: 8M-9-A-5
DATE: 1-16-96
COUNTY: IREDELL

SOIL SITE EVALUATION FOR ON-SITE WASTEWATER SYSTEM

APPLICANT: SUNWOOD BUILDERS
ADDRESS: PO Box 5877
STVL, NC 28677
OWNER AGENT: ✓ PHONE: 872-0922
APPLICATION DATE: 12/27/95 DATE EVALUATED 1/16/96
PROPOSED FACILITY: 3BR D/W MH
PROPERTY SIZE: 0.60 ACRE
LOCATION OF SITE: PINE RIDGE LOT #5
WATER SUPPLY: On-site Well ___ Comm. Well ___ Public ___ Other ✓ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	1940 LANDSCP POS / SLOPE(%)	HORIZON DEPTH (IN)	.1941 (a)(1) TEXTURE	.1941 (a)(2) STRUCTURE	.1941 (a)(3) MINEROLOGY	MATRIX COLOR	MOTTLE COLOR	OTHER PROFILE FACTORS
1	L	0-18	C	SBK	1:1 / FI			.1942 Wetness Cond. -
	6%	18+	ROCK					.1943 Depth/.1956 Sapr. -
								.1944 Restrictive Hori. - 4
								.1948 Profile Class. - 4
								Profile LTAR -
2	N	0-4	SC	GR	1:1 / VFR			.1942 Wetness Cond. -
	6%	4-14	C	SBK	1:1 / FI			.1943 Depth/.1956 Sapr. -
		14+	ROCK					.1944 Restrictive Hori. - 4
								.1948 Profile Class. - 4
								Profile LTAR -
3	L	0-6	SC	GR	1:1 / VFR			.1942 Wetness Cond. -
	4%	6-22	C	SBK	1:1 / FI			.1943 Depth/.1956 Sapr. -
		22+	ROCK					.1944 Restrictive Hori. - 4
								.1948 Profile Class. - 4
								Profile LTAR -
4	L	0-6	SC	GR	1:1 / VFR			.1942 Wetness Cond. -
	4%	6-28	C	SBK	1:1 / FI			.1943 Depth/.1956 Sapr. -
		28+	ROCK					.1944 Restrictive Hori. - 4
								.1948 Profile Class. - 4
								Profile LTAR -

AVAILABLE SPACE (.1945) ___ OTHER FACTORS (.1946) ___ SITE CLASSIFICATION (.1948) 4

SYSTEM TYPE ___ LONG-TERM ACCEPTANCE RATE(S) ___

EVALUATED BY: STEVE HENDRICK OTHER(S) PRESENT: PERRY JENKINS

COMMENTS: SITE UNSUITABLE DUE TO INSUFFICIENT SOIL DEPTH TO ROCK

0024163