I

06954

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR RANDALL McCOLLUM DATE 8-28-87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION I-40 west - T.R. on Old Mtn. Rd. - T.R. on 1st hardtop st. - approx. ½ mi. on left. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. 70 FT. SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 4 No. Bathrooms 2.5 Character & Porosity of Soil Grey Suitable.

Garbage Disposal Unit Yes ( ) No (✓) Percolation Rate 5 min/in.


Auto. Dishwasher Yes (✓) No ( ) Topography 2-6% Slope

Auto. Wash. Machine Yes (✓) No ( ) Depth to Water Table 10 ft

Site Suitable Yes (✓) No ( ) Rock or other impervious formations none observed.

Lot Area 2 acres

___ Basement with Plumbing ___ Basement without Plumbing ___ No Basement



Plot of System

Size of Tank 1250 Gals.

Nitrification Field:

No. of Lines 4

Sq. Ft. 960 Linear Ft. 320

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Sterling Church

Installed by Sterrill Const.

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Steve Brown

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Steve Brown DATE 8-28-87

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold