DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Applicant / ~~OWNER~~: John Putnam — Owner APPLICANT: June Yarns
ADDRESS: 161 Yarns Dr. — APPLICATION DATE: 3-18-00 — DATE EVALUATED: 3/17
PROPOSED FACILITY: 3BR MH/Crawl — PROPOSED DESIGN FLOW (.1949): 360 — PROPERTY SIZE: 1.92 Ac.
LOCATION OF SITE: _____ — PROPERTY RECORDED: ~~Yes~~
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAR
1	6% Linear	0-7	SL		+- 24" BR/GY/GY				PS .3
		7-14	SCL						
		14-44	± SCL						
		44-48	± C/SC						
2	6% Linear	0-8	SL		6" BR/GY 12" GY/BR 34" SCL 48" GY/BR				PS .35
		8-12	SCL						
		12-24	± C						
		24-44	± C w/ Rock						
		44-48	SC						
3	6% Linear	0-15	SCL w/ Rock		40" BR/GY				PS .3
		15-40	± C w/ SCL						
		40-45	± C						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Trench Conv.	Shallow Gravity 50% Reduction
Site LTAR	.3	.2

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Bill Thelson
OTHER(S) PRESENT: _____