SHEET 1 OF 1

DEPARTMENT OF ENVIRONMENT, HEALTH & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

DRAFT

PROPERTY I.D.#: 8M-9-A-20
DATE: 11-16-95
COUNTY: IREDELL

SOIL SITE EVALUATION FOR ON-SITE WASTEWATER SYSTEM

APPLICANT: [illegible] OWNER__ AGENT: ✓ PHONE: 872-6695
ADDRESS: [illegible] APPLICATION DATE: 11-2-95 DATE EVALUATED 11-16-95
PROPOSED FACILITY: 3BR D/W MH
PROPERTY SIZE: 0.717 Ac ±
LOCATION OF SITE: TRENT RIDGE ESTATES, LOT # 20
WATER SUPPLY: On-site Well___ Comm. Well___ Public___ Other___ EVAL. METHOD: Auger Boring ✓ Pit___ Cut___

Profile	1940 Landscape Position / Slope %	Horizon Depth (in)	1941 (1931) Texture	(1932) Structure	(1933) Mineralogy	Matrix Color	Mottle Color	Other Profile Factors
1	L	0-20	SC	WSBK	1:1 / FR			.1942 Wetness Cond. PS @ 30
	8%	20-48	C	SBK	1:1 / FI			.1943 Depth/.1956 Sapr. S
								.1944 Restrictive Hori. S
								.1948 Profile Class. PS
								Profile LTAR 0.3
2	C	0-20	SC	WSBK	1:1 / FR			.1942 Wetness Cond. PS @ 32
	10%	20-48	C	SBK	1:1 / FI			.1943 Depth/.1956 Sapr. S
								.1944 Restrictive Hori. S
								.1948 Profile Class. PS
								Profile LTAR 0.3
3								.1942 Wetness Cond. -
								.1943 Depth/.1956 Sapr. -
								.1944 Restrictive Hori. -
								.1948 Profile Class. -
								Profile LTAR -
4								.1942 Wetness Cond. -
								.1943 Depth/.1956 Sapr. -
								.1944 Restrictive Hori. -
								.1948 Profile Class. -
								Profile LTAR -

AVAILABLE SPACE (.1945) S OTHER FACTORS (.1946) NONE SITECLASSIFICATION (.1948) PS

SYSTEM TYPE CONV. GRAVITY LONG-TERM ACCEPTANCE RATE(S) 0.3 GPD/FT2

EVALUATED BY: S.G. HUDDLE OTHER(S) PRESENT: ERNEST H. RUNGE, LES JACKSON

COMMENTS: SUBSURFACE INTERCEPT DRAIN

00204.3