07026

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Tim DAGENHART DATE 4-11-88. PERMIT NO.

PHONE: Business Home

LOCATION Miracle Farm Rd. off Old Mtn. Rd. - gravel 1 mi. - T.R. on drive. Trailer by pond from farm drive - house at end of drive. S. R. No.

SUBDIVISION NAME LOT NO. SECTION OR BLOCK NO.

House (✓) Mobile Home ( ) Business ( ) Other

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Gray Suitable
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	5 min/1 in.
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-6%
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	10'
			Rock or other impervious formations	none encountered.


Lot Area Ample

___ Basement with Plumbing ___ Basement without Plumbing ___ No Basement

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 2
Sq. Ft. 120 Linear Ft. 240
Depth of Stone in Lines 12

Water Supply: Individual (✓)
Public ( )



Installed by James Hudler

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed:

IMPROVEMENTS PERMIT BY Steve Brown

COMMENTS: Flow divider used.

The location of the proposed SUN ROOM addition does not appear to impact the existing septic system. **NOTE: KEEP MINIMUM 25' FROM WELL
R. S. HEDRICK REHS
Date: APRIL 28, 2011
ICHD-Environmental Health Division

CERTIFICATE OF COMPLETION BY Steve Brown DATE 7-11-88.

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold