DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Francine Parker APPLICANT: Same
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: ___
PROPOSED FACILITY: 3BR MH/Rem PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: 3.5 Ac
LOCATION OF SITE: ___ PROPERTY RECORDED: Yes
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed
Lot # 18 Flint Ridge

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAF
1	8% Linear	0-12	dl sbk	Fr/Firm SE/P					PS .35
		12-36	cl w/ sl sbk	fr ss sp SE/P					
		36-46	Sap	fr ns np SE/P					
2	9% Linear	0-24	Sl	Fr ss sp SE/P					B .3
		24-36	"	Fr ns np SE/P					
		36-46	"	ns np SE/P					
3	8% Linear Rip	0-23	sl	Fr SE/P	mod/com				PS .3
		23-36	cl	sbk fr ss sp SE/P					
		36-48	cl/sap	sbk fr ss sp SE/P	Need Subsurface	area drainage	well drained	ditch downslope	
4									

Septic Tank
drainage 10 ft
up slope
side slope 15 ft
down slope 25 ft

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Gravity Conv.	Gravity 50% Reduction
Site LTAR	.35	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: Bill Johnson
OTHER(S) PRESENT: ___