Hulda Woody
Elenor Hilty

09610

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Billy R. McMillan DATE 2-10-89 PERMIT NO. 10C.

PHONE: Business _____ Home _____

LOCATION Hwy 90 W-T.L. on Signal Tower Rd. go ½ mi. T.R. into dev. - 1st left on Rockridge Dr. S. R. No. _____

SUBDIVISION NAME HAPPY ACRES. LOT NO. 33 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1 Character & Porosity of Soil Sandy Loam Suitable

Garbage Disposal Unit Yes ( ) No (✓) Percolation Rate _____


Auto. Dishwasher Yes ( ) No (✓) Topography Level

Auto. Wash. Machine Yes (✓) No ( ) Depth to Water Table 24"

Site Suitable Yes (✓) No ( ) Rock or other impervious formation: Hard Ground

Lot Area 2 Acre

Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Size of Tank 1000 Gals.

Distribution Field:
No. of Lines 2
Sq. Ft. 120 Linear Ft. 240
Depth of Stone in Lines 12"

Water Supply: Individual ( )
Public (✓)

Installed by Jason Hudson

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Steve Brown

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Steve Brown DATE 2-10-89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspections Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

- Zoning Clearance
- Health
- Bldg Permit

50.00