DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ of ____
PROPERTY ID #: ____
COUNTY: ____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Thomas Chase Hamby
ADDRESS: ____
PROPOSED FACILITY: 3 bR Hom
PROPOSED DESIGN FLOW (.1949): 360.12
LOCATION OF SITE: Rt 64 Tw L Lane Farm TR F-H Rt to RR
WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other ____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed


APPLICATION DATE ____
DATE EVALUATED: ____
PROPERTY SIZE: 17,500 Ft²
PROPERTY RECORDED: ____

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 15% 490	0-6	gr / L	vfr / SO	>48	>48	-	-	PS 0.3
		6-38	SBK / C	F: / SO					
		38-48	mSBK / CLAYEY	Fr / SO					
2	L / 5% 590	0-4	gr / L	vfr / SO	>48	>48	-	-	PS 0.3
		4-36	cBK / C	F: / SO					
		36-44	mSBK / CLAYEY	Fr / SO					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	II	II
Site LTAR	0.3	0.3

OTHER FACTORS (.1946): PS
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: TCH
OTHER(S) PRESENT: ____

COMMENTS: ____


970
Soil Site evaluation attachment
90
100
1339
100
100
175
175
175
17
100
175
18
100
19
100
TRAILWAY DR
100
100
100
N
W
E
S
1 inch equals 40 feet